

CERTIFICATE OF COMPLIANCE

Certificate Number 20190617-BP8812
Report Reference BP8812-20151002
Issue Date 2019-JUNE-17

Issued to: SARGENT & GREENLEAF INC
1 SECURITY DR
NICHOLASVILLE KY 40356-2159

This certificate confirms that representative samples of HIGH-SECURITY ELECTRONIC LOCKS, TYPE 1
REFER ADDENDUM PAGE FOR MODELS


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL Subject 2058 – High-Security Electronic Locks
Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20190617-BP8812
Report Reference BP8812-20151002
Issue Date 2019-JUNE-17

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

High Security Electronic Lock,
Type 1. Model 3006 Audit Pivot Lock with 31KP Keypad and Model 3007 (DIRECTDRIVE LOCK) Lock with Model 31KP-1xx or 31KP-2xx Keypad. Locks may be suffixed A-Series.

High Security Electronic Lock,
Type 1. Model 3028 and 3029 Locks with 31KP-1xx or 31KP-2xx Keypad. Locks may be suffixed A-Series.

Models 3006 and 3007, may be additionally suffixed -1xx, -2xx, -3xx. May also be suffixed by -5XX

Models 3028 and 3029 may be additionally suffixed -1xx, -2xx, -3xx May also be suffixed by -5XX



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

